J. EGEG ROCKY FLATS

INTEROFFICE CORRESPONDENCE

DATE:

September 20, 1994

TO:

S. K. Stovall, Plant Services, Bldg. 124, X4370

FROM:

R. A. Shoultz, Field Operations, Bldg. 080, X8879

SUBJECT:

WINTER FREEZE PROTECTION - RAS-011-94

Ref:

S. K. Stovall Itr, SKS-262-94, to Distribution, Same Subject, August 30, 1994

DOE Order:

4700.1

Action

None

All Environmental Operations facilities managers were contacted on September 14, 1994. They confirmed that one of the areas has an impaired or out-of-service system which would be effected by the up-coming winter months.

The Field Treatability Unit heat trace at Operable Unit two is currently being worked and repairs are due to be completed the first week in October 1994.

RAS:bk

cc:

M. C. Broussard

M. C. Burmeister

J. R. Cirillo

L. A. Gregory-Frost

A. K. Schmiechen

M. T. Vess

R. R. Wisehart

ADMIN RECCRD

BZ -A-00240